



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program June 12, 2013

Reviewed: PPB

|   |                                       |
|---|---------------------------------------|
| <b>Mine Name:</b> Pandora Mine  | <b>Permit Number:</b> M/037/0012      |
| <b>Operator Name:</b> Energy Fuels Resources  | <b>Inspection Date:</b> June 12, 2013 |
| <b>Inspector(s):</b> M. Bradley, W. Western   | <b>Time:</b> 2:00 pm                  |
| <b>Other Participants:</b> Andrea Reither, Ryan Ellis, Becky Doolittle, Race Fisher | <b>Mine Status:</b> active            |

| Elements of Inspection  | Evaluated                           | Comment                             | Enforcement              |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds                            | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls)         | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control                      | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4. Deleterious Material   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety)           | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 6. Reclamation  | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 8. Soils  | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Revegetation   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |

**Bond Renewal Date:** 09/20/2015 **Bond Amount:** \$175,811 **Annual Permit fee:** Paid

**Purpose of Inspection:** Temporary closure inspection, familiarization

**Inspection Summary:** Portals and shafts have been temporarily sealed using locked chain link fence, foam block, cinder block and/or steel plate. Discussed proposed reclamation activities to regrade and revegetate. EFR periodically has a few employees show up to do maintenance work and move things around to deter vandals.

No photos were taken to document site conditions.

**Conclusions and Recommendations:** Scavenge and stockpile topsoil prior to regrading waste rock piles. Old buildings remain; those structures not intended for later use should be dismantled and removed along with other scrap and waste materials. OGM to continue periodic inspections and monitor the site when in the area.

**Inspector's Signature**

MPB:eb

cc: Frank Filas, Energy Fuels Resources  
Becky Doolittle, BLM

<P:\GROUPS\MINERALS\WP\M037-SanJuan\M0370012-Pandora\draft\INSP-06132013.doc>

